

# AAXICO TECHNICAL SERVICES PRODUCT RELEASE



**AAXICO Technical Services (ATS) is pleased to announce PMA  
on the following Part Number:**


OEM	Description	OEM P/N	Embraer P/N	Approved Replacement PMA P/N	Eligibility
C & D Interiors	<b>No Smoking/ Fasten Seat Belt Sign</b>	56135-6441009-503	6441009-503	<b>BR9488-001ATS</b>	Embraer 145

**Advantages of Product Improvement:** Longer Life than Incandescent OEM; LED Light which Saves on Maintenance Costs for Airlines; Reduced Power Consumption; Less Heat and Higher Reliability.

Contact any AAXICO office listed below for pricing or payback analysis.



Corporate Headquarters \* Miami, Florida \* Tel: +1-305-592-4633 \* Fax: +1-305-592-6828 \* SITA: MIAXSXD  
 European Office \* Hampshire, England \* Tel: +44 (0)1730 268641 \* Fax: +44 (0)1730 268701 \* SITA: LGWXSXD  
 Southern Africa Office \* Johannesburg \* Tel: +27 11 9786440 \* Fax: +27 11 9786374  
 Asia-Pacific Office \* Singapore \* Tel: +65 64835003 \* Fax: +65 64835002 \* SITA: SINSXSD  
 China Office \* Beijing\* Tel: +86-10-64382701 \* Fax: +86-10-64382725  
[www.aaxico.com](http://www.aaxico.com) \* [sales@aaxico.com](mailto:sales@aaxico.com)

FIG. ITEM	PART NUMBER	AIRLINE STOCK NUMBER	NOMENCLATURE	VENDOR CODE	EST. FROM TO	UNITS PER ASSY
01	 6441000-503		SIGN ASSY, NS/F50 (SEE CHAPTER 25)			REF
10	6441014-503		...SIGN, NS/F50	50135		1
20	060300FE		...PCB ASSY	86135		1
			...LAMP, T1 24-FIN			4

- ITEM NOT ILLUSTRATED

33-23-04

Fig. 01  
Page 1  
May 17/01


PARTS MANUFACTURER APPROVAL NO. PQ1565CE  
PRODUCTION APPROVAL LISTING-SUPPLEMENT NO. #34  
DATE: October 21, 2003

FEDERAL AVIATION ADMINISTRATION-PARTS MANUFACTURER APPROVAL

AAXICO Technical Services  
8881 NW 13 Terrace  
Miami, Florida 33172  
(305) 592-4633

Part Name	Part Number	Approved Replacement For	FAA Approval Basis and Approved Design Data	Installation Eligibility: Make	Installation Eligibility: Model
No Smoking / Fasten Seat Belt Sign Housing	BR9488-001ATS	Embraer P/N 6441009-503	Identityity Per CFR Part 21, Section 21.303(c)(4), Dwg No. BR9488ATS.Rev N/C, dated 6/13/03 or later approved revision.	Embraer	Emb-145
Sign, No Smoking/Fasten Seat Belt	82000 -73201ATS	S4171503-4 (Boeing)	Fest and Computation Per CFR Part 21 Section 21.303(c)(4), Dwg No: 82000-732XXATS, Rev: N/C, Date: 09/23/03 or later FAA approved revision	Boeing	767 Series

EMB 145 Illustrated Parts Catalog  
SIGN, NS/FSB Sheet 1



**A**

